

Installation Prcedure for c-Bridge Software 03-01-15

1. Install CentOS 5.x 32 bit or CentOS 6.x 64 bit
2. If using the iptables firewall, or any external firewall, open up and forward the following ports to the CentOS installation:
 - a. Ports 42420 through 42431 – TCP and UDP
 - b. Ports 49152 through 65535 UDP (These are ports used by IP Site Connect. They do not need to be open for installing the c-Bridge software, but should be opened up when the software installation is finished)
3. Log in as 'root'.
4. Enter the following commands at the Linux prompt.
 - a. `cd /root`
 - b. `wget cbridge-download.rayfield.net:42420/GetFile?name=v_installer&unix=1 -O v_installer`
 - c. `chmod +x v_installer`
 - d. `./v_installer`
5. Wait 3 mins.
6. From another computer, browse to `http://xxx.xxx.xxx.xxx:42420/` (where xxx.xxx.xxx.xxx is either the local IP address of the c-Bridge, if accessing it from the same LAN, or the public IP address of the c-Bridge if accessing it from the internet)
7. Log in as:
 - a. User = admin
 - b. Password = tlnet
8. Go to Config/General System.
9. Click on "Supplementary ID"
10. Enter the serial number and secret phrase (run key)